6 Recommendations

The following recommendations have been:

- continue monitoring of all groundwater bores (old and new)
- continue monitoring salinity in all bores (old and new)
- perform a more detailed investigation of the sub-surface basalt and its impact on the groundwater systems and salinities in the Timor West targeted area.