

GENERAL DESCRIPTION

Very steep, high hills with huge areas of granite rock outcrop, soils are very shallow where present. Slopes are 25-50%. Mt BECKWORTH

LAND ASSESSMENT

- A Erosion Risk with Land Disturbance
 - Class 5 Very steep slopes, shallow soils very rapid runoff
- B Constraints on Construction
 - Class 5 Very steep rocky slopes
- C Effluent Disposal by Soil Absorption
 - Class 5 To steep & rocky. Insufficient soil
- D Small Farm Dams
 - Class 5 To steep & rocky

OVERALL ASSESSMENT FOR RURAL SUBDIVISION 2-10 ha (Considering A, B, C & D)

Class 5 Very steep rocky slopes