

LAND CAPABILITY SURVEY OF THE YOU YANGS FOREST RESERVE

By

G. L. Guy

LAND CAPABILITY SECTION

Published February, 1978

SOIL CONSERVATION AUTHORITY

378 Cotham Road, Kew
Victoria 3101.

TABLE OF CONTENTS

Summary	4
Introduction	5
Description of the Land	6
(a) General	6
(b) Physical Features	6
(i) Climate	6
(ii) Geology and Physiology	6
(iii) Soil.....	6
(c) Mapping.....	6
Land Capability	10
(a) General	10
(b) Rating Systems for Land Based Recreation	10
(c) Using the Rating Tables	10
(d) Assessment – Summary.....	10
Discussion	14
Erosion	14
Seasonal Moisture Variation	14
Site Location and Conflict.....	14
Salinity	14
Reticulated Water	14
Acknowledgements	15
References	16

LIST OF TABLES

Table 1 - Soils of the You Yangs Area.....	7
Table 2 - Topography And Map Units	9
Table 3 - Activities Involved In Different Kinds Of Land Based Recreation	11
Table 4 - Summary Sheet	12
Table 5 - Land Capability Assessment – Summary.....	13
Table 6 - Land Capability Rating for Car Parks and Roads	17
Table 7 - Land Capability Rating for Intensive Uses Areas	18
Table 8 - Land Capability Rating for Camp Sites	19
Table 9 - Land Capability Rating for Paths & Trails.....	20
Table 10 - Land Capability Rating for Building Foundations for Light Structures.....	21
Table 11 - Land Capability Rating for on-Site Effluent Disposal	22
Table 12 - Land Capability Rating for Playing Fields	23
Table 13 - Land Capability Rating for Earthen Dams	24
Table 14 - Land Capability Rating for Road Fill	25
Table 15 - Land Capability Rating for source of Topsoil.....	26
Table 16 - Land Capability for source of Sand.....	27
Table 17 - Map Unit: Ss	28
Table 18 - Map Unit: Ho	29
Table 19 - Map Unit: H	30
Table 20 - Map Unit: Ro	31
Table 21 - Map Unit: R	32
Table 22 - Map Unit: U	33
Table 23 - Map Unit: U	34
Table 24 - Map Unit: Dl	35
Table 25 - Map Unit: Scf.....	36
Table 26 (b) - Laboratory Analysis	42

LIST OF FIGURES

Fig 1 – Diagrammatic Representation of the Survey Area	8
--	---

LIST OF PLATES

Plates 1 & 2 – Intensive use has compacted and denuded many areas	43
Plate 3 – Surface runoff from steeper areas can increase the erosion hazard	44
Plate 4 – Severe gully erosion running through the reserve has been initiated by sand scraping operations in adjacent areas.....	44
Plate 5 – The existing walking track to Flinders Peak is ill-defined, devoid of vegetation and badly eroded.....	45
Plate 6 – An alternative track to Flinders Peak exists and could be used to rest the main track.....	45
Plate 7 – Sand extraction operations have cleared and exposed large areas. Restoration will be both difficult and expensive.	46

APPENDICES

Appendix 1 - The Rating Systems	17
Appendix 2 - Capability Analysis	28
Appendix 3 - Soil Information.....	37
(a) Description of Representative Soil profiles	37
(b) Laboratory analysis.....	41

SUMMARY

Land Capability rating systems have been applied to the map units in order to define and identify natural limitations for selected land uses.