

Appendix 1.2 – List of Roadside Landslides Noted by the Shire

Landslide No.	Road	Location	Remarks	Proposed Works	Estimated Cost \$
1	Rogers Road	Lot 72 at Moe 200m above Thorpdale Road junction	Sheared at road. Part of an old slip	Piling retaining wall and backfill	10 000
2	Yarragon-Thorpdale	Lot 13, Parish of Moe	Sheared road recent fill (3 years)	Benching and graded backfill	6 000
3	Trafalgar-Thorpdale	Lot74A, Parish of Moe	Sheared at road recent fill (5 years)	Almost stable, tree planting, road reinstatement	5 000
4	Sunny Creek	Lot 44A, Parish of Moe	Sheared at edge of bitumen	TOE Retaining wall and graded fill and backfill	10 000
5	Sunny Creek	Lot 48A, Parish of Moe	Road sheared	Benching drainage and backfill	7 000
6	Allambee-Childers	Lot 19, Parish of Warragul	Road subsiding	Appear stable road reinstatement	5 000
7	Mirboo-Yarragon	Lot 17A, Parish of Allambee East	Half road subsided	Major road realignment drainage and tree plating on slip	35 000
8	Yarragon-Leongatha	Lot 3, Sec A, Paris of Allambee East	Slip below road starting to affect roadway	Retain wall at toe of slip	12 000
9	Narracan Connection	Lot 104, Parish of Moe	Above Nail.	Improved drainage (Surface and subsoil)	6 000
10	Trafalgar-Thorpdale	Lot 73, 74 & 74A, Parish of Moe	Road subsiding and slipping down hill. Maintenance required.	Instatement of road Slip treatment unknown road reinstatement only	3 000
(11)	Petits Track	Lot 23, Parish of Narracan, Pt CA 4D & 4E, SEC Sub	Road subsided and slipped down hill	Improved drainage and tree planting. Road reinstatement	15 000
12	Trafalgar-Thorpdale (Giles)	Lot 64, Parish of Moe	This has been walled & appears to have stabilized	Appears stable	Nil
13	Childers Settlement (Castello)	Lot 52, Parish of Allambee East	Material slipping onto road	Retaining wall improved drainage and tree planting	12 000
(14)	North Shire	Lot Parish of	Material slipping onto road	Retaining wall and tree planting	12 000
15	Rogers Road	Lot 92, Parish of Moe	Affects approx 50 metres	Remove top three ft of road and reconstruct improved drainage and tree planting	18 000
16	Weits	Lot 108, Parish of	Road has not slipped but material from above is constantly being carted off road	Retaining wall, divert drainage tree planting	10 000

Landslide No.	Road	Location	Remarks	Proposed Works	Estimated Cost \$
17	Moe-Thorpdale	Lot 106, Parish of Moe Narracan side of Weir's Rd junction	Road constantly dropping necessitating constant filling	Actual slip treatment not known road reinstatement	5 000
18	Moe-Thorpdale (Hillbricks)	Lot Parish of	Material slipping onto road has been removed often	Retaining wall improved drainage (Surface and subsoil)	5 000
19	Dingley Dell	Lot 17, Parish of Allambee East	Material slipped across road. Road impassable.	As outlined in CRB report	100 000
20	Allambee-Thorpdale	Lot 67, Parish of Allambee East	Road subsiding continuous filling required. Road must be kept open because of Dingley Dell	Slip treatment not known. Road reinstatement	10 000